


CONNECT

GameCom® X95™:

1. Place batteries in headset.
2. Connect the wireless adapter to the Xbox.
3. Press the Power button for 2 seconds to turn the headset on. The headset and the adapter should connect immediately (see LED status on reverse).
If you cannot hear anything through your headset, try adjusting the volume up or restarting the game or application.

If headset is still not paired (see LED status on reverse) you can manually pair your headset and adapter.

From powered off state, press the Power button for 6 seconds until LED begins to flash rapidly. Release the button; headset is now in pairing mode.



On wireless adapter: press the Pair/Connect button on the wireless adapter for 6 seconds until the LED flashes rapidly. Release button; headset and adapter should now be paired.

TROUBLESHOOT

HEADSET

STATUS/CONDITION	LED STATUS OR ACTION
Paired/connected	LED solid blue flash
Pairing	LED rapid blue flash
Not connected	LED slow blue flash
Pairing fails	If pairing mode times out, LED changes from rapid flash to headset power off
Power off	2 second button press, LED gets bright then turns off
Power on	Press the Power button for 2 seconds, LED comes on to appropriate status
Low battery	LED triple blue flashes
Auto shut down	Headset shuts down after defined period of time with no signal from wireless adapter

WIRELESS ADAPTER

STATUS/CONDITION	LED STATUS OR ACTION
Paired	LED solid blue flash
Pairing	LED rapid blue flash
Not connected	LED slow blue flash
Pairing fails	If pairing mode times out, LED goes into "not connected" state